

Summary

This profile provides an overview of water, sanitation and hygiene (WASH) infrastructure within Camp 6 in Ukhia, Cox's Bazar. Primary data for the sixth round was collected between 22 April - 12 May 2018.¹ Findings should be considered indicative only. The full camp dataset is available on [HDX](#).


Site Overview

# of individuals:	26,938
# of households:	6,062
# of shelters:	3,420
# of individuals per shelter:	7.9

Key WASH Infrastructure

# of latrines: (% functional and safe ²):	733 (82%)
# of improved water sources: ³ (% functional):	305 (86%)
# of washrooms:	322

Location Map






Water Access

Three most commonly identified types of water points, by functionality:




Key sectoral standards:

	Target	Current Round	Achievement
# of people per functional improved water source ³	max. 250	103	
% of shelters with at least 1 functional improved water source ³ within 200m	100%	100%	
% of functional improved water source with no latrine within 10m	100%	30%	


Sanitation

Latrine characteristics:


Functionality and safety




Functionality







Safety







Lighting



Key sectoral standards:

	Target	Current Round	Achievement
# of people per functional (non-full) and safe latrine ²	max. 20	45	
# of people per functional (non-full) latrine	max. 20	43	
# of people per safe latrine ²	max. 20	40	
% of shelters with at least one functional and safe latrine ² block within 50m	100%	99%	

Targets based on long term WASH Sector Standards / Indicators for the Rohingya response, Sphere Minimum Standards as well as Department of Public Health and Environment (DPHE) Minimum Standards.  Minimum standard/indicator reached,  75-99% of the minimum standard reached, or within 25% of minimum standard reached,  50-74% of the minimum standard reached, or within 26-50% of minimum standard reached,  Less than 50% of minimum standard reached, or within greater than 50% of minimum standard reached.


¹ REACH enumerators conducted a full sweep of all sites and camps (as per boundaries defined by ISCG) and used a Kobo form to log all key infrastructure observed during this sweep.

² 'Safe' refers to fully covered latrines (i.e. a latrine with four walls, a roof and a lockable door).

³ This includes handpumps / tubewells, tapstands and water tanks.







Water Access



	Functioning	Non-functioning		
Hand pump / tubewell	230	42	Shelter	
Tapstand	8	1	Camp boundary	
Well	1	1	River	
Water tank	23	1	<i>The boundaries and names used on this map do not imply official endorsement or acceptance by the United Nations</i>	
Unimproved water source	5	2		

Sanitation



	Functioning	Non-functioning	
Latrines	● 216	● 28	Shelter 
WASH rooms	■ 269		Camp boundary 
			River 

The boundaries and names used on this map do not imply official endorsement or acceptance by the United Nations

